



Solo Checklists

After Landing/Clear Of Runway

1. Flaps.....RETRACT
2. Carburetor Heat (If Required)OFF
3. Mixture**DO NOT LEAN FOR TAXI**
4. Landing LightOFF
5. Taxi Clearance/AdvisoryCONTACT

Before Takeoff/Cleared For Takeoff

1. FlapsAS REQUIRED
2. Carburetor HeatOFF
3. Landing Light.....ON
5. Advisory/Tower.....CONTACT
6. TrafficCHECK

TOUCH AND GO'S ARE NOT AUTHORIZED ON SOLO FLIGHTS